



HIGH QUALITY AIRBRUSH TECHNOLOGY

Informations about marks on needles, nozzles and air caps

For better differentiating about the sizes, look at the marks on nozzles, needles and air caps.

Harder & Steenbeck

needle	size	mark
	0.15	none
	0.2	none
	0.4	=====
	0.6	=====
	0.8	none
	1.0	=====
	1.2	=====

nozzle	size	mark
	0.15	=====
	0.2	none
	0.4	=====
	0.6	=====
	0.8	none
	1.0	=====
	1.2	=====

air cap	size	mark
	0.15	none
	0.2	none
	0.4	=====
	0.6	=====
	0.8	none
	1.0	=====
	1.2	=====

Hansa

needle	size	mark
	0.2	=====
	0.3	=====
	0.4	=====

nozzle	size	mark
	0.2	=====
	0.3	=====
	0.4	=====

air cap	size	mark
	0.2	=====
	0.3	=====
	0.4	=====